

6754 So. 4000 W
Spanish Fork, UT
84660

m/045/064 Feb. 10, 2005

Dear Sirs:

We do not feel seeding the quarry
from which Dan Meyer has been
hauling rock is necessary.

Sincerely yours
Jackson R. Fitzgerald

RECEIVED

FEB 14 2005

DIV. OF OIL, GAS & MINING